

October 15, 1967
804 De Clark St.
Beaver Dam, Wis.

Dear Bob,

I am sending you a copy of some work we did in Langlade County. We were told C.T.H. "A" was to be rebuilt in the area where the Wisconsin Power And Light Co. owns a 40 acre tract of land. The section corner common to sections 9 - 10 - 15 & 16, T 33 N - R 12 E was indicated on a highway map, along with a reference monument. There was also an "iron rod" indicated on the print, marking the northwest corner of the NE $\frac{1}{4}$ of the NE $\frac{1}{4}$ of section 16. The highway print indicated the reference monument will be in the way of construction, so I decided to locate the corner and establish new ties that could be used in the future. I know you are interested in such control for the area, so for that reason I'm sending you all the information we found and a description of what we have done to this date.

We dug up the pipe marking the section corner. It was about 2 feet below the surface of the road. We then proceeded to the northwest corner of the NE $\frac{1}{4}$ of the NE $\frac{1}{4}$ of section 16. We found the "iron rod" indicated on the highway print, it turned out to be a double barreled shot gun barrel just west of a fence post. About 5 feet east of this point we found the remains of an old cedar post, measuring about 4" x 4" square. The post had split in two, with half of it still standing in a circle of hard heads. On one side of the cedar post 1/16 had been carved. The remains of the base of the cedar post was still evident below the ground level and within the circle of hard heads. We then replaced this point with a 2" x 30" pipe and a brass cap and left the remains of the cedar post. We then established a line between the section corner and the 1/16 corner. The line was measured, a solar bearing taken, and the ties taken from the section corner to the foundation of a tavern.

I realize this is not a very complete job of surveying, but time would not permit us to do a proper survey of the "forty" in question. My main concern was to tie the section corner for future surveys. The location of the 2" pipe at the 1/16 corner was a means of preserving the evidence we found, as I felt road construction might very well destroy all evidence of the hard heads and cedar post. When time permits we will probably survey the "forty".

I wanted you to know what has been done to this date, so that if you were to survey in the area you could weigh the evidence as we found it. You may also know the origin of the cedar post, I must confess that my knowledge of surveys in this area is next to nothing.

Sincerely,

Tom Appaquin

RECORD #

10493

LANGLADE COUNTY SURVEYORS OFFICE

DATE FILED: 12/28/98

BY: D. LUSTY

DATE

LOCATION

T33N - R12E - Section 16

WISCONSIN POWER AND LIGHT COMPANY

SCALE

1" = 200'


DR. BY

DWG. NO.

Found REMAINS OF 4"x4" CEDAR POST, "1/16" CARVED ON SIDE ROCKS AROUND POST. REPLACED POST WITH 2"x30" IRON PIPE AND BRASS CAP.

1331.1'
N 89° 36.5' W (SOLAR BEARING)
C.T.H. "A"

TIES ARE TAKEN TO CONCRETE FOUNDATION CORNERS. TIES ARE NOT DRAWN TO SCALE.



Found 1 1/2" IRON PIPE FILLED WITH CONCRETE AT SECTION CORNER ABOUT 2' BELOW THE SURFACE OF THE ROAD

