
I, WILLIAM F. KELLY, REGISTERED LAND SURVEYOR, VERIFY THAT I HAVE CHECKED THE LOCATION OF AN EXISTING IRON PIPE ON THE N.E. CORNER OF LOT 16 OF THE ASSESSORS PLAT OF GOVERNMENT LOTS 1 AND 2 IN SECTION 11 - T.34N.-R.11E.

I FIND THAT THE PIPE IS LOCATED ON THE NORTH LINE OF SAID LOT NO. 16 IN ACCORDANCE WITH THE ASSESSORS PLAT. THERE IS A DIFFERENCE IN THE EAST-WEST MEASUREMENTS BETWEEN THE TOWN ROAD AND THE SHORE LINE AS SHOWN ON THE SKETCH ATTACHED.

DATE: 5-12-77



12