

4301128 0020 2023

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

HISTORY OF ORIGINAL CORNER ESTABLISHMENT AND SUBSEQUENT RESTORATION AND DESCRIPTION OF ANY RECORD, MONUMENT OCCUPATIONAL, TESTIMONIAL OR OTHER EVIDENCE CONSIDERED:

THE ORIGINAL CORNER WAS SET BY BRADLEY IN 1854 WITH THE ORIGINAL BEARING TREES OF:  
12" MAPLE N44°E 9 LINKS  
8" ELM S58°E 32 LINKS  
1912 HUTCHINSON MEASURED THE NORTH - SOUTH 1/4 LINE  
1982 KELLY SET A 2" IRON PIPE WITH BRASS CAP  
2023 I FOUND THE 2" IRON PIPE AND SET ADDITIONAL TIES

● = LOCATION OF CORNER

|  |  |    |   |
|--|--|----|---|
|  |  |    |   |
|  |  |    |   |
|  |  | 28 |   |
|  |  |    | ● |

SECTION 28  
TOWNSHIP 30 NORTH, RANGE 11 EAST  
TOWN OF ROLLING  
LANGLADE COUNTY, WISCONSIN

CORNER WAS: (CHECK ALL THAT APPLY)

- ☐ RESTORED THROUGH ACCEPTANCE OF AN OBLITERATED EVIDENCE LOCATION
- ☒ RESTORED THROUGH ACCEPTANCE OF A FOUND PERPETUATED LOCATION
- ☐ CONSIDERED A LOST CORNER AND REESTABLISHED THROUGH LOST CORNER PROPORTIONATE METHODS (INCLUDE A PLAN VIEW DRAWING SHOWING DISTANCES AND DIRECTIONS TO OTHER PUBLIC LAND SURVEY CORNERS USED FOR PROPORTIONING AND DETERMINING THE CORNER LOCATION)
- ☐ RESTORED OR REESTABLISHED IN A LOCATION THAT DIFFERS FROM A PREVIOUS RESTORATION OR REESTABLISHMENT (INCLUDE A PLAN VIEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND)
- ☐ CHECK IF THERE IS ADDITIONAL INFORMATION ON BACK

DESCRIBE THE MONUMENT AND ACCESSORIES USED TO PERPETUATE THE LOCATION OF THE CORNER. (INCLUDE A PLAN VIEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND) ALSO INCLUDE FOUR TIES TO THE SECTION CORNER AND DESCRIPTION OF THE TIES.


○ SET 3/4" X 30" RE-BAR  
WEIGHING 1.50 LBS/FT

● FD 1" I. PIPE

● FD WITNESS MONUMENT

BEARINGS REFERENCED TO  
THE LANGLADE COUNTY  
COORDINATE SYSTEM

T SET 6 FOOT WHITE T-POST




CHARLEY G. BRINKMEIER

(Type or print name) CERTIFY THAT THE CORNER LOCATION SHOWN ON THIS RECORD WAS DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS U.S. PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

SIGNATURE

OCT 20 2023  
DATE



11-30-11  
INDEX NO.

CERTIFIED LAND CORNER RESTORATION

Index No. V-11


State of Wisconsin }  
County of LANGLADE } ss.

I WILLIAM F. KELLY, do hereby  
certify that on the 12<sup>th</sup> day  
of JAN., 1982, I found  
evidence of the S. 1/4  
corner of SECT. 28  
Township 30, North, Range  
11 EAST, Fourth Principal Meridian,  
as described hereon; and that from this evidence  
I established a new monument and accessories  
as described hereon to perpetuate the original  
location of this corner.



Resident witnesses:

History of original corner establishment:  
ORIGINAL CORNER ESTABLISHED BY  
WM T. Bradley IN OCT, 1853.

Description of corner evidence found:  
SET A 2" x 42" BLACK IRON PIPE  
WITH BRASS CAP MONUMENT.



Description of monument and accessories I established to perpetuate the original location of this corner.



Dated at ELCHO, Wis., this 12<sup>th</sup> day of JAN., 1982.

Signature William F. Kelly Title COUNTY SURVEYOR Registration No. 1098  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within  
instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_  
at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

\_\_\_\_\_  
(Register of Deeds)

By \_\_\_\_\_ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE

43011280020

○ = Corner monument restored.