

LANGLADE COUNTY U.S. PUBLIC LAND
SURVEY MONUMENT LOCATION RECORD

4310824 0000 2614

SECTION 30
TOWNSHIP 31 N
RANGE 9 E
ACKLEY
CITY, VILLAGE, TOWN
SECTION

FOUND ☒ LANDMARK ☐ BENCHMARK ☐
SET ☐
RESET ☒
RE-TIED ☒

CORNER IDENTITY: NW CORNER SEC. 30 (BERNTSEN SNM-1 NAIL)
LANGLADE COUNTY COORDINATE: N: 343410.4250
E: 549719.4210

ELEVATION-(FEET): _____ DATUM: _____
WEATHER: CLEAR AND SUNNY
DATE OF SURVEY: 8/12/2014 TEMPERATURE: 75 °F
SURVEY PARTY: CHRIS FIERI & IAN FIELD

BASIS FOR MONUMENT LOCATION:

(DESCRIBE METHOD OF SURVEY AND CORNER AUTHENTICATION)

3/29/1990 - William Kelly S-1098 recovered an existing stone monument at this corner position. Set a P.K. Nail over the stone and made four (4) reference monuments to perpetuate the corner location.

5/10/1994 - Barrientos and Associates visited this corner and recovered the P.K. Nail of record along with all four (4) witness monuments from the previous tiesheet. They set four (4) Bernitsen 3" x 30" magnetic aluminum monuments to comply with DOT specs.

8/12/2014 - I recovered a Bernitsen SNM-1 Nail at the corner location. I also recovered all eight (8) reference monuments from the previous tiesheet. Returned to the corner after the re-surfacing of State Highway "64" and set a Bernitsen SNM-1 Nail at the corner location.

FIELD BOOK NO. S-12 PAGE NO. 62
COMPANY RIVERSIDE LAND SURVEYING LLC


LOCATION
(Indicated By X)

WISCONSIN
CHRISTOPHER L. FIERI
S-2954
WESTON, WI
LAND SURVEYOR

CERTIFIED CORRECT:
Christopher L. Fieri
CHRISTOPHER L. FIERI S-2954
Registered Land Surveyor
DATE: 10-9-2014

TIE SKETCH:


- ☒ - BERNTSEN SNM-1 NAIL SET
- ☐ - 1" O.D. IRON PIPE FOUND
- ☐ - WISDOT ALUMINUM MONUMENT FOUND
- ☐ - LANGLADE COUNTY ALUMINUM WITNESS MOMUMENT FOUND
- ☐ - 3/4" IRON BAR W/ DOT CAP FOUND
- ☐ - 2" IRON PIPE FILLED W/ CONCRETE FOUND



4310824 0000

Attachment to Tie Sheet Q-25, T31N, R8E

I visited corner on 08/14/2013; Book 6, pg. 55. I found a P.K. Nail at the corner location and four WisDOT stamped Aluminum Monument reference ties. The P.K. Nail did not match the intersection of the existing ties. I removed the P.K. Nail and set a Berntsen Survey Marker Nail at the intersection of said reference ties.

 7/27/15

Anthony R. Dallman, PLS-2405

Lincoln County Surveyor



RECORD AND CERTIFICATION OF U.S.
PUBLIC LAND SURVEY CONTROL STATION


Wisconsin Department of Transportation

District	Project ID	Located By	
7	9015-06-70	R.B. JOHNSON - SURVEY CREW CHIEF	
Corner	Township	Range (E.W)	County
N.W. COR. SEC. 30	31 N	9 E	LANGLADE
Wisconsin Coordinates	East (X)	North (Y)	Elevation (A)
BY BARRIENTOS	2,148,168.203	479,847.553	
Control Station Name	East (X)	North (Y)	Elevation (A)

Horizontal -	NORTH AMERICAN, 1927	CONTROL DATUM	MEAN SEA LEVEL, 1929 ADJUSTMENT
		Vertical -	
Horizontal -	Order	SURVEY CONTROL	Order
		Vertical -	


SKETCH

43108240000



LOCATION SKETCH
(Location of landmark indicated by "X")

11/94 SET PK NAIL
P.T. FROM THESE TIES
FROM THE
D. Hedy



I hereby certify that on the date of MAY 10, 1994
the above corner was located by a marker and/or references established by

BARRIENTOS & ASSOC. (registration no.)

I further certify that to perpetuate the location of said corner, on the date of

MAY 10, 1994 at the exact location thereof,
a permanent marker or witness monuments consisting of

FOUR 3" x 30" MAGNETIC ALUMINUM

BERNITZ JEAL MONUMENTS

were located as shown above.

Jack R. Wallin - SURVEY COORDINATOR

Signature (District Survey Supervisor)

Dave Linder 5/23/94

- ADDITIONAL TIES -
FROM CORNER TO:

1. 3/4" IRON PIPE

537° 36' E - 82.71'

2. 4" CONC. FILLED IRON PIPE

532° 36' W - 70.03'

3. WISDOT R/W RE-13AR

40° 22' E - 51.98'

4. LANGLADE CO. WITNESS COR.

N 0° 19' E - 65.95'

R-1

4310824000


U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.
● = Corner monument restored.

ORIGINAL CORNER ESTABLISHED
BY HIRAM C. FELLOWS IN 1860.





- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

SET PK NAIL OVER SQUARE STONE MONUMENT, FOUND IN PLACE.


- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)
Describe witness monuments.

- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

BT's:



ⓧ NAIL SET IN BASE



N 34° W
72.46'

6 HWY. 647


PK NAIL SET OVER
EXISTING SQ. STONE MON.

S 39° E
82.79'

1" IRON PIPE

ACKLEY PINE RIVER ROAD

5" BALSAM



R-1

43108240000

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and, (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

NONE

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(2)

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

No.

(i) I, WILLIAM F KELLY R.L.S 1098
(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William F. Kelly
Signature

3-29-90
Date

