

4341007 2000 2025


U S PUBLIC LAND SURVEY MONUMENT RECORD - ADDENDUM

NOTE: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7.08 U.S. Public Land Survey Monument Record (3) (a-f)

A-E 7.08(3)(a) Identity of corner:
EAST 1/4 CORNER SECTION 07,
TOWNSHIP 34 NORTH,
RANGE 10 EAST OF THE 4TH PM,
TOWN OF ELCHO,
COUNTY OF LANGLADE

WISCONSIN - LANGLADE COUNTY

N: 452,434.254 USft (XXX,XXX.XXX)
E: 587,525.318 USft (XXX,XXX.XXX)
Datum: NAD83 (2011)
GNSS Method RTK
GNSS Control WISCONSIN VRS



The coordinate value shown has been verified by the average of two or more GPS observations at a markedly different time. Coordinates shown in parenthesis are previously published values.

A-E 7.08(3)(b)

Original Surveyor: J. L. Nowlin

Date of Original Survey: July 8, 1865
Completed: July 20, 1865

Original Accessories:
Birch: 6
Birch: 6

N 45° W: 17 Links
S 65° E: 3 Links


See previous U.S. Public Land Corner Restoration - G-5 34-10 - April 21, 1998 - Surveyor 1390 - David E. Tlusty.

THENCE:

March 9, 2023 - I found a 4" diameter pipe with a brass cap affixed to the top.

I also found the 1937 stone with a chiseled 'x' on top, a white vinyl T-post, and Kelly's 3 bearing tree witnesses (nails by Tlusty), the maple is alive and in good condition, both birch are dead and standing.
I established 2 new reference monuments as shown below.

A-E 7.08(3)(c)(d) Plan view of corner with references to at least 4 witness monuments.



A-E 7.08(3)(e) 1865 Surveyor set a post, 1939 Surveyor found a 4" boiler tubing filled with concrete, surmounted by a brass cap, on which is stamped the corner location, 1998 Surveyor found a brass capped 4" diameter iron pipe. I found a 4" diameter pipe with a brass cap affixed to the top.

A-E 7.08(3)(f) I accept this monument as a FOUND PERPETUATED LOCATION of the corner.
A-E 7.08(3)(g)(h) This corner was not determined through lost-corner-proportionate methods.

A-E 7.08(3)(i) I, Jeffrey L. DeMuth, Professional Land Surveyor No. S-2656, hereby certify that the corner location on this record was determined by me or under my direction and control, and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge, and belief.



Jeffrey L. DeMuth

SIGNATURE

March 22, 2023

DATE

LANGLADE COUNTY
U.S. PUBLIC LAND CORNER RESTORATION

The East 1/4 corner of Section 7, T. 34 N., R. 10 E., Langlade County, WI.

Corner was: (check all that apply)

- ☐ Restored through acceptance of an obliterated evidence location.
- ☒ Restored through acceptance of a found perpetuated location.
- ☐ Determined to be lost and re-established through proportionate methods.
- ☐ Show bearings and distances to PLSS corners used for proportioning, and show original distances).
- ☐ Restored/recovered/re-established in a location that differs from a previously established position.
- (Show difference in plan view below).
- ☐ Check here if addition information is shown on the reverse side of this form.

Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence and all other evidence considered in the recovery/restoration of the corner.

The original corner was established in 1865 by James L. Nowlin. Original bearing trees: birch, 6", N45°W, 17 lks., and a birch, 6", S65°E, 3 lks. In 1937 Hintz described this corner as: "To original 1/4 corner, remains of original BT birch, 12", S50°E, 24 lks. New BO: stone, West, 14.1 lks." In 1975, former surveyor Kelly found 4" brass cap set in concrete in a pipe (iron). Corner is located on edge of a ridge in a stand of hardwoods. Made 3 new BT's: w. birch, 6", S57°W, 11.30'; w. birch, 8", N63°W, 9.57' and a hard maple, 6", N61°E, 13.50'. On April 21, 1998 D. Tlusty, D. Williams found iron pipe with 4" brass cap, straightened it and made solid. Found 1937 stone with chiseled "x" on top, N86°W, 9.2'. Also found old fence north and west (both down) and all Kelly's B.T.'s. Accepted monument found as the best evidence of the original corner location and freshened with blue paint, added B.T. signs and aluminum tie nails in a new low blaze on the side of the trees and remeasured as shown below.

Physical description of the monument set:

For the corner, I left the existing monument in place.

Set white vinyl sign post on the south side of the monument.


Describe the accessories used to perpetuate the corner. Include a plan view drawing and accessories found/set. Describe measuring point on bearing trees. Show any topographic

LEGEND


- ☐ 2" iron pipe found
- ☒ 4" iron pipe w. brass cap fnd
(unless noted otherwise)
- ☒ 3/4" x 30" re-bar set flush
- ☐ white vinyl sign post set

Bearings magnetic with hand compass.

Trees are blazed, painted blue and have "Bearing Tree" signs attached. Tree ties are measured to an aluminum nail in a low blaze on the side of the tree shown as: >



Index No. G - 5 34-10



O = corner perpetuated
The East 1/4 corner
of Section 7,
T. 34 N., R. 10 E.,
Langlade County, WI


I, David E. Tlusty, Registered Land Surveyor, as Langlade County Surveyor, certify that the corner location on this record was determined by me and that this U.S. Public Land Survey Monument Record is correct to the best of my knowledge and belief.

FORM 985 M. G. MILLER CO., MILWAUKEE

State of Wisconsin }
County of LANGLADE } ss.

I WILLIAM F. KELLY, do hereby
certify that on the 8th day
of APRIL, 1975, I found
evidence of the 1/4 SECTION
corner of SECTION 7 & 8
Township 34, North, Range
10 EAST, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:
J. DREW



○ = Corner monument restored.


CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Description of corner evidence found:

FOUND 4" BRASS CAP SET IN CONCRETE IN A 4" PIPE.
CORNER LOCATED ON EDGE OF A RIDGE IN A STAND OF HARDWOODS.

Description of monument and accessories I established to perpetuate the original location of this corner.



4" BRASS CAP
MARKED:
CORNER WITNESSED
WITH NEW BEARING
TREES.

NBT BLAZED ON TRUNK AND A +
MARK ON BASE OF NEW BEARING
TREES.


Dated at ELCHO, Wis., this 8th day of APRIL, 1975.

Signature William F. Kelly Title REGISTERED LAND SURVEYOR Registration No. S1098
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within
instrument was filed in this office for record on the _____ day of _____, 19____
at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy



William F. Kelly

Index No. 6-5

