

The attached document is a portion 10446 as originally received. The entire original document, when scanned, was too large for most email programs.

Although the 4 four pages of 10446 are very hard to read, they contain background information on these notes and the surveying process.

RECORD # 10227
LANGLADE COUNTY SURVEYORS OFFICE
DATE FILED: 6/1/15 BY: D. TUSTY

Dependent Resurvey of the East Boundary of
T. 29 N., R. 12 E., 4th Prin. Mer., Wisconsin.

Chains	A hemlock stump, badly rotted, bears N. 63° E., 20 lks. dist.
	A hemlock stump, badly rotted, bears S. 72° E., 10 lks. dist.
	A hemlock stump, badly rotted, bears S. 63° W., 39 lks. dist.
	A hemlock stump, badly rotted, bears N. 54° W., 50 lks. dist.
	And new bearing trees:
	A poplar, 6 ins. diam., bears N. 59° E., 119 lks. dist., mkd. T 30 N R 13 E S 31 B T.
	A cedar, 6 ins. diam., bears S. 33° E., 76 lks. dist., mkd. T 29 N R 13 E S 6 B T.
	A cedar, 9 ins. diam., bears S. 54° W., 44 lks. dist., mkd. T 29 N R 12 E S 1 B T.
	A poplar, 5 ins. diam., bears N. 45° W., 80 lks. dist., mkd. T 30 N R 12 E S 36 B T.
	Land, gently rolling. Soil, sandy, 3rd rate, on upland; muck, 3rd rate, in swamp. Timber, pine, hemlock, oak, ash, elm, maple, birch and poplar on upland; tamarack, balsam, spruce and cedar in swamp; undergrowth, same, very dense.

Dependent Resurvey of the East
Boundary of T. 30 N., R. 12 E.,
of the 4th Prin. Mer., Wisconsin,
as originally surveyed by William
J. Neely, U.S. Deputy Surveyor,
in 1852 and 1853.

N. 1° 00' W., bet. secs. 31 and 36.
Over gently rolling land, through hardwood and pine
timber.

The point for the 1/4 sec. cor., is determined by
existing local and patrol evidence.

At point for cor.,

Set a cylindrical concrete monument, 24 ins. long,
6 ins. diam., 20 ins. in the ground, surrounded by a
mound of stone, for 1/4 sec. cor., with a brass
tablet, 24 ins. diam., 3 in. stem, embedded in top,
mkd.

1/4

836 S 31

3533

from which

-138-

Dependent Resurvey of the East Boundary of
T. 30 N., R. 12 E., 14th Prin. Mer., Wisconsin.

Chains	
	The cor. point was determined by the intersection of the center line of a road bearing N., and a N. and S. fence line. George Schmidt, a nearby land owner, stated that the original corner was on the N. and S. fence line at this point.
	And new bearing trees:
	An elm, 10 ins. diam., bears N. 28 $\frac{1}{2}$ ° E., 34 lks. dist., mkd. 1/4 S 31 B T.
	A poplar, 7 ins. diam., bears S. 47 $\frac{1}{2}$ ° E., 58 lks. dist., mkd. 1/4 S 31 B T.
	Thence
9.70	N. 0° 12' E.
	Enter low swampy land, bears NW. and SE., ash, elm and alder.
14.70	Leave swampy land, bears NW. and SE.; enter cedar and tamarack swamp.
39.94	The point for the cor. of secs. 25, 30, 31 and 36, as determined from the remains of original bearing trees.
	At point for cor.,
	Set a cylindrical concrete monument, 24 ins. long, 6 ins. diam., 20 ins. in the ground, for cor. of secs. 25, 30, 31 and 36, with a brass tablet, 3 $\frac{1}{2}$ ins. diam., 3 in. stem, embedded in top, mkd.
	T 30 N R 12 E S 30 S 31 1933 from which Remains of original bearing trees:
	A cedar stump, uprooted, badly rotted, bears N. 76° E., 32 lks. dist.
	A stump hole, bears S. 25° E., 12 lks. dist.
	A fallen ash stump, badly rotted, bears S. 77° W., 24 lks. dist., with signs of original blaze.
	A fallen cedar stump, badly rotted, bears N. 54° W., 29 lks. dist.
	And new bearing trees:
	A cedar, 8 ins. diam., bears N. 49 $\frac{1}{2}$ ° E., 50 lks. dist., mkd. T 30 N R 13 E S 30 B T.
	A cedar, 10 ins. diam., bears S. 50 $\frac{1}{2}$ ° E., 91 lks. dist., mkd. T 30 N R 13 E S 31 B T.

-139-

Dependent Resurvey of the East Boundary of
T. 30 N., R. 12 E., 14th Prin. Mer., Wisconsin.

Chains	
	A cedar, 5 ins. diam., bears S. 39° W., 149 lks. dist., mkd. T 30 N R 12 E S 36 B T. A spruce, 8 ins. diam., bears N. 20½° W., 109 lks. dist., mkd. T 30 N R 12 E S 25 B T. Land, gently rolling. Soil, sandy, 3rd rate, on upland; muck, 3rd rate, in swamp. Timber, pine, oak, ash, elm, maple, birch, hemlock and poplar on upland; cedar and tamarack in swamp; undergrowth, same.
1.55	N. 0° 32' W., bet. secs. 25 and 30.
37.53	Over swamp, through dense cedar and tamarack.
39.15	Leaves swamp, through dense cedar and tamarack.
39.78	Barbed wire fence, bears E. and W. Fence parallel road, bears N. and SE.
	The point for the 1/4 sec. cor., as determined from existing local evidence.
	At point for cor.,
	Set a cylindrical concrete monument, 24 ins. long, 6 ins. diam., 27 ins. in the ground, 3 ins. below surface, for 1/4 sec. cor., with a brass tablet, 3/4 ins. diam., 3 in. stem, embedded in top, mkd. 1/4 925 S 30 1933 from which
	The corner point was determined by the intersection of the center line of Wis- consin Highway No. 47, bearing S. and W., and a N. and S. fence line. And new bearing trees: A hemlock, 14 ins. diam., bears S. 88½° E., 153 lks. dist., mkd. 1/4 S 30 B T. An elm, 14 ins. diam., bears S. 39½° E., 132 lks. dist., mkd. 1/4 S 30 B T. A round highway post, painted white, bears S. 0° 30' W., 84 3/10 lks. dist. A round highway post, painted white, bears N. 0° 30' E., 60 9/10 lks. dist.
	Thence
9.65	N. 0° 34' W. Fence, parallel to road, bears E. and W.

-140-

Dependent Resurvey of the East Boundary of
T. 30 N., R. 12 E., of the 4th Prin. Mer.,
Wisconsin.

Chains										
40.03	The point for the cor. of secs. 19, 24, 25 and 30, as determined from the remains of the original bearing trees. At point for cor., Set a cylindrical concrete monument, 24 ins. long, 6 ins. diam., 20 ins. in the ground, for corner of secs. 19, 24, 25 and 30, with a brass tablet, $\frac{3}{4}$ ins. diam., 3 in. stem, embedded in top, mkd. <table><tr><td>T 30 N</td><td>R 12 E</td><td>R 13 E</td></tr><tr><td></td><td>S 24</td><td>S 19</td></tr><tr><td></td><td>S 25</td><td>S 30</td></tr></table> 1933 from which Remains of original bearing trees: A maple stump, badly rotted, bears S. 58$\frac{1}{2}$° E., 16 lks. dist., showing signs of original blaze. A hemlock stump, rotted to ground, bears N. 57° W., 25 lks. dist. And new bearing trees: A hemlock, 12 ins. diam., bears N. 80$\frac{3}{4}$° E., 5$\frac{1}{2}$ lks. dist., mkd. T 30 N R 13 E S 19 B T. A hemlock, 10 ins. diam., bears S. 37$\frac{1}{2}$° E., 159 lks. dist., mkd. T 30 N R 13 E S 30 B T. An elm, 12 ins. diam., bears N. 43° W., 82 lks. dist., mkd. T 30 N R 12 E S 24 B T. Land, gently rolling. Soil, sandy, 3rd rate. Timber, pine, hemlock, elm, ash, oak, birch, maple and poplar.	T 30 N	R 12 E	R 13 E		S 24	S 19		S 25	S 30
T 30 N	R 12 E	R 13 E								
	S 24	S 19								
	S 25	S 30								
10.30	N. 0° 11' W., bet. secs. 19 and 24.									
14.70	Over gently rolling land, through pine and hardwood timber.									
33.87	Enter cedar swamp, bears E. and W.									
36.50	Creek, 10 lks. wide, 4 ins. deep, course W.									
39.94	Creek, 5 lks. wide, 2 ins. deep, course SE.									
	Leave swamp, bears NW. and SE.									
	The point for the $\frac{1}{4}$ sec. cor., which is marked by a cedar post, 6 x 6 x 36 ins. above the ground, set by a former county surveyor from the original bearing trees.									
	At point for cor.,									
	Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with									

Dependent Resurvey of the East Boundary of
T. 30 N., R. 12 E., 4th Prin. Mer., Wisconsin.

Chain	brass cap mkd. 1/4 s24 s19 1933. from which
	Remains of original bearing trees: A spruce, uprooted, bears N. 56° E., 22 lks. dist., with original blaze and scribe marks showing. A hemlock, stump, rotted to ground, bears S. 40° W., 16 lks. dist. And new bearing trees: A hemlock, 8 ins. diam., bears N. 88° E., 75 lks. dist., mkd. 1/4 S 19 B T. A hemlock, 10 ins. diam., bears S. 66 1/2° W., 16 lks. dist., mkd. 1/4 S 24 B T. And local bearing tree: A hemlock, 22 ins. diam., bears S. 63 1/2° W., 26 lks. dist., mkd. 1/4 S B T.
13.00	Thence, N. 0° 04' E.
35.00	Enter cedar swamp, bears E. and W.
39.64	Leave swamp, bears E. and W.
39.88	Road, bears E. and W., winding.
	The point for the cor. of secs. 13, 18, 19 and 24, which is marked by a post, badly rotted, set by a former county surveyor from the original bearing trees. At point for cor., Set a cylindrical concrete monument, 24 ins. long, 6 ins. diam., 20 ins. in the ground, for cor. of secs. 13, 18, 19 and 24, with a brass tablet, 3 1/2 ins. diam., 3 in. stem, embedded in top, mkd.
	T 30 N R12E R13E s13 s18 s24 s19 1933 from which
	A poplar, 8 ins. diam., bears N. 20° E., 26 1/2 lks. dist., mkd. T 30 N R 13 E S 18 B T. An elm, 8 ins. diam., bears S. 64° E., 67 1/2 lks. dist., mkd. T 30 N R 13 E S 19 B T.

-142-

Dependent Resurvey of the East Boundary of
T. 30 N. 44, R. 12 E., 4th Prin. Mer.,
W. 1/4, 30 N. 44, R. 12 E., 4th Prin. Mer.,

Chains	An elm, 10 ins. diam., bears S. 55° 09' W., 282 lks. dist., mkd. T 30 N R 12 E S 24 B T. A poplar, 6 ins. diam., bears N. 43° W., 80 lks. dist., mkd. T 30 N R 12 E S 13 B T. Land, gently rolling. Soil, sandy, 3rd rate, on upland; muck, 3rd rate, in swamp. Timber, pine, hemlock, oak, ash, elm, birch, maple and poplar on upland; cedar and tamarack in swamps; undergrowth, same.
0.11.	N. 0° 24' W., bet. secs. 13 and 18.
39.75	Over gently rolling land, through pine and hardwood. Fence, parallel road, bears E. and W. • The point for the 1/4 sec. cor., as determined by existing local and parcel evidence. At point for cor., Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the 1/4 sec. cor., with brass cap, mkd. 1/4 sl3 sl8 1933 from which The corner point was established at a fence corner, fences bear W. and S. Adam Kakel, a nearby land owner, stated that the fence corner was placed at the point for the original corner by a local county surveyor. And new bearing trees: A maple, 18 ins. diam., bears N. 53° 40' E., 283 lks. dist., mkd. 1/4 S 18 B T. A hemlock, 16 ins. diam., bears N. 82° 05' W., 151 lks. dist., mkd. 1/4 S 13 B T. Thence N. 0° 33' W. Enter swamp, bears E. and W. Creek, 70 lks. wide, 2 ft. deep, course S. 70° E. Leave swamp, bears E. and W. The point for the cor. of secs. 7, 12, 13 and 18, which is marked by an iron pipe, 1 1/2 ins. diam., 8 ins. above ground, set by a former county
24.10	
25.00	
35.20	
39.74	

Dependent Resurvey of the East Boundary of
T. 30 N., R. 12 E., of the 4th Prine Mer., Wisconsin.

Chains	
	surveyor from the original bearing trees. At point for cor., Set a cylindrical concrete monument, 24 ins. long, 6 ins. diam., 20 ins. in the ground, for cor. of sec. 7, 12, 13 and 18, with a brass tablet, 3 1/2 ins. diam., 3 in. stem, embedded in top, mkd. 1933 from which Remains of original bearing trees: A birch stump, burned and rotted, 24 ins. diam., bears N. 59° E., 32 lks. dist. A fallen hemlock, 17 ins. diam., bears S. 50° E., 32 lks. dist., mkd. T 30 N R 13 S 18. A birch stump, burned and rotted, 30 ins. diam., bears N. 48 1/2° W., 65 lks. dist. And new bearing trees: A hemlock, 16 ins. diam., bears N. 72 1/2° E., 68 lks. dist., mkd. T 30 N R 13 S 7 B T. A basswood, 12 ins. diam., bears S. 75° E., 55 lks. dist., mkd. T 30 N R 13 S 18 B T. A maple, 8 ins. diam., bears S. 12 1/2° W. 1/2 T. 41 lks. dist., mkd. T 30 N R 12 E S 13 B T. Aspen, 6 ins. diam., bears N. 45 1/2° W., 76 lks. dist., mkd. T 30 N R 12 E S 12 B T. Land, gently rolling. Soil, sandy, 3rd rate. Timber, pine, hemlock, ash, oak, elm, maple, birch and poplar; undergrowth, same.
	N. 0° 36' E., bet. sec. 7 and 12. Over gently rolling land, through pine and hardwood.
1.00	Enter swamp, bears E. and W.
4.00	Leave swamp, bears E. and W.
11.50	Enter swamp, bears N. 10° W., and S. 30° E.
27.60	Leave swamp, bears N. 30° E., and S. 20° W., enter timber.
39.91	Proportionate dist., there is no remaining evidence of the original post or bearing trees.
	Set an iron post, 3 ft. long, 2 ins. diam., 27 in. in the ground, for the 1/4 sec. post, with brass cap mkd.

-144-

Dependent Resurvey of the East Boundary of
T. 30 N., R. 12 E., of the 4th Prin. Mer., Wisconsin.

Chains	
79.82	512 87 1933 from which A maple, 11 ins. diam., bears S. 73° E., 66½ lks. dist., mkd. 1/4 S 7 B T. An elm, 10 ins. diam., bears N. 54½° W., 81 lks. dist., mkd. 1/4 S 12 B T. The point for the cor. of secs. 1, 6, 7 and 12, which is marked by a stone, 7 x 7 x 3 ins. above ground, set by a former county surveyor, from the original bearing trees. At point for cor., Set a cylindrical concrete monument, 24 ins. long, 6 ins. diam., 32 ins. in the ground, for cor. of secs. 1, 6, 7 and 12, with a brass tablet, 3½ ins. diam., 3 in. stem, embedded in top, mkd. 512 87 1933 from which An elm, 14 ins. diam., bears N. 24° E., 428 lks. dist., mkd. 1/4 S 13 E S 6 B T. A spruce, 10 ins. diam., bears S. 76° E., 167 lks. dist., mkd. 1/4 S 13 E S 7 B T. A white pine, 14 ins. diam., bears N. 78½° W., 208 lks. dist., not marked. Corner falls in center of a road, bears N, and W. Land, gently rolling. Soil, sandy, 2nd rate, on upland; muck, 3rd rate, in swamps. Timber, pine, oak, ash, elm, birch, hemlock and poplar on upland; cedar and tamarack in swamp; undergrowth, same, dense.
40.24	N, 0° 15' W., bet. sec. 1 and 6. Over gently rolling land, through pine and hardwood timber, line in and along road. The point for the 1/4 sec. cor., as determined from the original bearing trees. At point for cor., Set a cylindrical concrete monument, 24 ins. long, 6 ins. diam., 24 ins. in the ground, for 1/4 sec. cor., with a brass tablet, 3½ ins. diam., 3 in. stem, embedded in top, mkd.

4-585

-145-

Dependent Resurvey of the East Boundary of
T. 30 N., R. 12 E., of the 4th Prin. Mer.,
Wisconsin.

Chains

1/4

51 1/2

1933

from which

Remains of original bearing trees:

A cherry, 16 ins. diam., bears N. 24° E.,
1 1/2 lks. dist., mkd. with original glass
and scribe marks 1/4 S B T.

And new bearing trees:

An elm, 1 1/2 ins. diam., bears S. 66 1/2° E.,
57 lks. dist., mkd. 1/4 S B T.

A sugar maple, 20 ins. diam., bears N.
37 1/2° W., 116 lks. dist., mkd. 1/4 S B T.

Thence

N. 0° 45' W.

53.96

The closing sp. cor. of Sp. 30 N., Rs. 12 and 13
E., heretofore described,

land, gently rolling.

Soil, sandy, 2nd rate.

Timber, pine, hemlock, ash, oak, elm, birch, maple
and poplar; undergrowth, rare

Resurvey completed Nov. 4, 1933.