



10368

RECORD #

LANGLADE COUNTY SURVEYORS OFFICE

53

DATE FILED: 3/4/94 BY: D.T.



See Vol 173 Pg 177

Also Vol 169 Pg 325

DESCRIPTION OF SUBSTA. SITE

Commencing at the center of Section 13-34-10, A 4"x8" blue stone with x in top. Thence North on a section line 1336' to a section corner, a 1"x4" iron rod in the ground. Thence by an angle to the right of 97°33', 260' to an iron pipe in the ground, this is the place of beginning. Thence by an angle to the left of 6°34', 100' to an iron pipe in the ground. Thence by an angle to the right of 30°00', 100' to an iron pipe in the ground. Thence by an angle to the right of 30°00', 100' to an iron pipe in the ground. Thence by an angle to the right of 30°00', 100' to the place of beginning. All in the Township of Elcho, Langlade County, Wisconsin.

WISCONSIN PUBLIC SERVICE CORP.			
PLAT OF ELCHO SUBSTATION ELCHO, LANGLADE COUNTY WIS.			
Rev. & Check December 28, 1951	J.A.H.	DATE 11-14-33	SCALE 1"=200'
REVISIONS	CHIEF ENGINEER		