DAVID E. TLUSTY, RLS LANGLADE COUNTY SURVEYOR
837 Clermont Street 715-627-6311 Antigo, WI 54409-0505

MAP OF SURVEY

For Langlade County Highway Dept., the Schroeder Pit, in the Southeast Quarter of the Northeast Quarter of Section 34, Township 31 North, Range 11 East, Langlade County, Wisconsin.



DESCRIPTION OF LINE SURVEYED

The South line of the parcel described in Document No. 268281, Langlade County records, being a parcel in the Southeast Quarter of the Northeast Quarter of Section 34, T.31N., R.11E., said line being more particularly described as follows: Commencing at the East Quarter corner of said Section 34, thence N89°55'10"W, along the South line of said SE-NE, 1467.20 feet; thence N0°39'12"E, along the West line of said SE-NE, 825.71 feet to the point of beginning of said line; thence N78°11'17"E, along the South line of the parcel described in Doc. No. 268281, 67.59 feet to an iron pipe set; thence continuing N78°11'17"E, along said South line, 955.24 feet to an iron pipe set; thence continuing N78°11'17"E, along said South line, 1.08 feet to the point of termination of said line.

I, David E. Tlusty, Registered Land Surveyor and Langlade County Surveyor, do hereby certify that by the direction of Tim Rusch, Langlade County Highway Commissioner, I have made a survey of the South line of the parcel described in Document No. 268281, Langlade County records, being a parcel in the Southeast Quarter of the Northeast Quarter of Section 34, Township 31 North, Range 11 East, Town of Antigo, Langlade County, Wisconsin, as shown hereon. I further certify that this map is a true and correct representation of said survey and that this survey is correct to the best of my knowledge and belief.

March 28, 2014 David E. Tlusty, RLS

WISCONSIN
DAVID E. TLUSTY
S-1390
Deerbrook
WI
REGISTERED LAND SURVEYOR

RECORD # 10883
LANGLADE COUNTY SURVEYORS OFFICE
DATE FILED: 3/31/14 BY: D. TLUSTY